

ERRATA SHEET

**TENTATIVE ORDER NO. R9-2010-0096
 TENTATIVE ORDER NO. R9-2010-0096, AN ORDER
 MODIFYING ORDER NO. R9-2005-0149
 NPDES NO. CA0109088
 KNIGHT AND CARVER YACHTCENTER BOAT REPAIR
 FACILITY
 DISCHARGE TO SAN DIEGO BAY
 SAN DIEGO COUNTY**

The following revisions will be made to tentative Order No. R9-2010-0096. Some changes/corrections below are shown in underline/~~strikeout~~ format to indicate added and removed language, respectively.

Errata #	SECTION	REVISION
1.	Modification 14. Page 12	For this discharge, a mixing zone or dilution allowance is not authorized. The chronic instream waste concentrations (IWCs) for this discharge <u>are</u> 100% effluent and 62.5% effluent . A series of at least five effluent dilutions and a control shall be tested <u>as necessary to determine the TUC. At minimum, the</u> The dilution series shall include the IWCs and three dilutions below the IWCs (e.g., 100%, 62.5%, 50%, 25% and 12.5%) <u>as necessary to determine the TUC</u> .
2.	Modification 20. Page 17.	Ballast Water (Monitoring Locations BW-001 and BW-002)